CMI INC.

316 E. 9th St., Owensboro KY 42303
Phone 866-835-0690
Fax: 270-685-6268

SERVICE WORK ORDER

340991

DATE 3-21-17
RCVD VIA FEDX

BILL TO:

ATTN:

CITY STATE ZIP

CUSTOMER NO. 585013

PHONE

SHIP TO: ND Crime lab

ATTN:

2641 E. Main Ave.

CITY Bismarck STATE ND ZIP 58501

PHONE 701-328-6159

FAX 701-328-6185

MODEL # 8000 SERIAL # 80-0066668 BILL CODE 3

EXTRA PARTS RCVD
BT, PC, Sensor, battery

DESCRIPTION OF PROBLEM Turned on/off randomly

Infrared / Fuel Cell
PRELIMINARY TEST INFORMATION

BATTERY- EXT 12.12 V; INT 3.02 V

Unable to duplicate. Internal temp running high. Leak at sim return, o-ring stretched.

VERIFIED PROBLEM? No

WORK PERFORMED:

Replaced power supply for internal temp.
Repaired leak at sim return fitting and replaced o-ring.
Spoke with Roberta Nimmo and Charles Eder.

Miscellaneous
PRELIMINARY TEST INFORMATION

WORK PERFORMED:

KBV

PARTS USED

QTY	PART NO.	DESCRIPTION
1	120094	PWR Supply, 12V
1	471201	O-ring

REPAIR	CAL. ADJ.	CALIBRATON	FINAL
GTW			
½ HOURS 3	HOURS 0.5	HOURS 1.0	HOURS 1.0
DATE Sept 13, 17	DATE Sept 14, 17	DATE Sept 14, 17	DATE Sept 14, 17

SHIPPING STICKER HERE

SPECIAL SHIPPING INSTRUCTIONS