CMI INC.

316 E. 9th St., Owensboro KY 42303
Phone 866-835-0690
Fax: 270-685-6268

SERVICE WORK ORDER

402510

DATE	8-8-18
RCVD VIA	FEDX

BILL TO:	SHIP TO: ND Crime lab
ATTN:	ATTN: Charles Eder
	2641 E Main Ave
CITY / STATE / ZIP	CITY: Bismarck STATE: ND ZIP: 58501
CUSTOMER NO.: 585013	PHONE: 701-328-6159
PHONE:	FAX: 701-328-6185

MODEL #	SERIAL #		BILL CODE
8000	80-006690	002480ND	EW

EXTRA PARTS RCVD: BT, PC, gas box, battery

DESCRIPTION OF PROBLEM: EPROM error 18

Infrared / Fuel Cell
PRELIMINARY TEST INFORMATION

BATTERY- EXT 13.01 V; INT 3.02 V

System Error #18 on boot up.
External battery won't charge.
No other issues found.

VERIFIED PROBLEM? Yes

WORK PERFORMED:

Cleared system error and reinstalled form.
Replaced external battery.
Performed system checks.

Miscellaneous
PRELIMINARY TEST INFORMATION

WORK PERFORMED:

POR

PARTS USED

QTY	PART NO.	DESCRIPTION
1	013010	Battery, 12V
4	320384	MLX Crimp

REPAIR	CAL. ADJ.	CALIBRATON	FINAL
GTW	NOP	NOP	NOP
½ HOURS: 3	HOURS: 0.5	HOURS: 1.0	HOURS: 1.0
DATE: Aug 20, 18	DATE: Aug 23, 18	DATE: Aug 24, 18	DATE: Aug 24, 18

SHIPPING STICKER HERE

SPECIAL SHIPPING INSTRUCTIONS

FORM# CMI SWO REV (1)