CMI INC.

316 E. 9th St., Owensboro KY 42303
Phone 866-835-0690
Fax: 270-685-6268

SERVICE WORK ORDER

402594

DATE	8-22-18
RCVD VIA	FEDX

BILL TO:	SHIP TO: ND Crime Lab
ATTN:	ATTN: Roberta Grieger
	3641 E. Main Ave
CITY / STATE / ZIP	CITY: Bismarck STATE: ND ZIP: 58501
CUSTOMER NO. 585013	PHONE 701-328-6159
PHONE	FAX 701-328-6185

MODEL #	SERIAL #		BILL CODE
8000	50-JG1187	002420 ND	EW

EXTRA PARTS RCVD: BT, Jackson, Tray

DESCRIPTION OF PROBLEM: check power distribution board

Infrared / Fuel Cell
PRELIMINARY TEST INFORMATION

BATTERY- EXT 13.11 V; INT 3.01 V

Prints question marks continuously, +/- 15 volts missing from Power Dist. board

VERIFIED PROBLEM? Yes

WORK PERFORMED:

Replaced power distribution board. Performed system and update checks.

Miscellaneous
PRELIMINARY TEST INFORMATION

WORK PERFORMED:

NV

PARTS USED

QTY	PART NO.	DESCRIPTION
1	021283G01T	PwbAssy, Power

REPAIR	CAL. ADJ.	CALIBRATON	FINAL
GTW	NP	NP	NP
½ HOURS 4	HOURS 0.5	HOURS 1.0	HOURS 1.0
DATE Sep 7, 18	DATE Oct 5 18	DATE Oct 5 18	DATE Oct 5 18

SHIPPING STICKER HERE

SPECIAL SHIPPING INSTRUCTIONS

FORM# CMI SWO REV (1)