

CHAIN OF CUSTODY  
BREATH ALCOHOL INSTRUMENT

Instrument: 8000 Serial Number: 80-005946

Agency being assigned instrument: CM1

Date 10 June 15

Transferred from:

Name (print) Deb Kasher

Signature Deb Kasher

Agency Crime Lab

Transferred to:

Name (print) \_\_\_\_\_

Signature \_\_\_\_\_

Agency CM1

Reason for transfer/remarks:

Battery (external) isn't staying "trained".  
Does not hold a charge & the display  
reads "Battery low" at 92%.

Or Shipped Via:

USPS \_\_\_\_\_ UPS \_\_\_\_\_ FedEx \_\_\_\_\_ Other \_\_\_\_\_

Date Sending Instrument: \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_ Air Bill No. \_\_\_\_\_



# Service Evaluation Form

This form **MUST** be completed and enclosed with instrument to be serviced.  
Failure to complete and return this form may cause delays in service.

(Note: please ship items in their original shipping container(s) or a similar protective box.)

1. Contact information: Customer Number 585013 (contact Customer Service)  
 Name Deb Kashur Phone: (701) 328-6159  
 Fax: (701) 328-6185 Email: dkashur@nd.gov

2. Bill to Address: Under warranty Ship to Address: N.D. Crime Laboratory  
2641 E. Main Ave  
Bismarck, ND 58501-5044

3. Serial Number: 80-005946 Instrument Model: 8000

4. Detailed Description of Problem:  
External battery issue. When plugged in, battery charges properly to 100%, but when power button is off & in box is discharging the ~~bat~~-display reads "Battery low" at only 92%. We're having problems "training" these batteries. We've tried 2 or 3 different  
**\*\*\*Hazardous Material Warning! - DO NOT return gas cylinders with instrument!\*\*\* batteries.**

I Authorize Repairs Up To:  All  \$250  \$500  \$750  Other \$ \_\_\_\_\_  
 Purchase Order Number (attach a copy of P.O. if applicable) \_\_\_\_\_

Authorized By: Under warranty  
Deb Kashur Forensic Scientist II Ship to:  
 Name (Please Print) Title  
Deb Kashur 10 June 15  
 Signature Date

CMI, Inc.  
 Attn: Service Dept.  
 316 East Ninth Street  
 Owensboro, KY 42303

No, please send estimate before repairs are made.  
 Note: An estimate will be faxed before performing any repairs and may cause delays in service.  
 An evaluation fee (\$79.00 or actual costs) will apply to estimates that are not repaired.