



SERVICE WORK ORDER

DATE	2-8-19
RCVD VIA	UPS

316 E. 9th St., Owensboro KY 42303
 Phone 866-835-0690
 Fax: 270-685-6268

410327a

BILL TO:

ATTN:

CITY STATE ZIP

CUSTOMER NO. 585013

PHONE

SHIP TO: ND office of Attorney General

ATTN: Crime Lab / Charles Edgar

2641 E - Main Ave.

CITY STATE ZIP
 Bismarck ND 58501

PHONE
 701-328-6159

FAX
 701-328-6185

MODEL # 8000	SERIAL # 80-407093	002150ND	BILL CODE EW
--------------	--------------------	----------	--------------

EXTRA PARTS RCVD
 1BT, 1Box, Battery

DESCRIPTION OF PROBLEM
 Not flagging, MeOH interference

Infrared / Fuel Cell
 PRELIMINARY TEST INFORMATION

BATTERY- EXT 11.88V; INT 3.01V

DVM's erratic, source unstable.
 No other issues found.

VERIFIED PROBLEM? Yes

WORK PERFORMED:

Replaced source and reset preamp gains.
 Performed system checks.
 MeOH interference checked in Cal Lab - OK.

31 IDS

PARTS USED		
QTY	PART NO.	DESCRIPTION
1	020982	Source Assy

Miscellaneous
 PRELIMINARY TEST INFORMATION

20x18x18

WORK PERFORMED:

REPAIR GTW	CAL. ADJ. 0.5	CALIBRATION 1.0	FINAL 1.0
1/2 HOURS 4	HOURS 0.5	HOURS 1.0	HOURS 1.0
DATE Mar 1, 19	DATE Mar 4, 19	DATE Mar 5, 19	DATE Mar 5, 19

SHIPPING STICKER HERE

SPECIAL SHIPPING INSTRUCTIONS