



INTOXILYZER® 8000 INSTALLATION AND REPAIR CHECKOUT
OFFICE OF ATTORNEY GENERAL
CRIME LABORATORY DIVISION
Toxicology Section/Breath Alcohol Program
SFN 59281 (03-2014)

Serial Number <i>80-005944</i>	Instrument Location <i>BSPD</i>
Reason for Install/Repair <input checked="" type="checkbox"/> Install After Receiving From Crime Laboratory <input type="checkbox"/> Install After Location Change <input type="checkbox"/> Other (Specify) _____	

Check When Done:

- 1. Surge Protector Installed/Properly Grounded.
- 2. Telephone Line Connected to Intoxilyzer® 8000.
- 3. Breath Tube Heated.
- 4. Enter Preliminary Data (i.e. Date, Time, DST (Y), and Location; Level 2, Function E).
- 5. Scan/Enter Gas Cylinder Information (Level 1, Function S).
- 6. Run Tests:
 - A. Print Test (Level 1, Function P).
 - B. ACA Test (Level 1, Function C).
 - C. RFI Test (CMS Mode or Level 1, Function B or C; Key Radio During Test).
- 7. Repair and/or Maintenance Performed (if Any): *None*
- 8. Complete the Top Portion of the Intoxilyzer® Record (SFN50496, Form 120-G) and Place it by the Intoxilyzer® for Use.
- 9. File Previous Intoxilyzer® Record (SFN50496, Form 120-G) at the Intoxilyzer® Location at the Agency.
- 10. Send the Following to the Crime Laboratory: Completed Intoxilyzer®8000 Installation and Repair Checkout (SFN59281, Form 104-G), Print Test, ACA Test, and RFI Test.

Field Inspector Signature <i>Pat Reay</i>	Date <i>7-28-16</i>
Reviewed By (Crime Laboratory Use Only) <i>Deb Shanaver</i>	Date <i>28 July 16</i>

Intoxilyzer Test Record and Checklist
NDOAG Crime Lab. Div., Bismarck, ND 58501

CMI, Inc. Intoxilyzer Alcohol Analyzer
North Dakota Model 8000 SN 80-005944
Location = BSPD 8164.13.00 06/09
07/28/2016 09:46

***** Printer Test *****

abcdefghijklmnopqrstuvwxyz1234567890-=_|
ABCDEFGHIJKLMNopqrstuvwxyz!@#\$\$%^&*()_+?

abcdefghijklmnopqrstuvwxyz1234567890-=_|
ABCDEFGHIJKLMNopqrstuvwxyz!@#\$\$%^&*()_+?

Current Instrument Setup

Data Entry Mode: Enabled
Start Test Sequence: DABACABA
Display Prelim Rslt? Yes
Display Third Digit? Yes
Inhib Printer(Y/N)? No
Display Volume? No
Disable On Memfull? Yes
of Print Copies? 1
Select Std (D/W/I)? Dry
Standard Value? 0.080
Standard Lot #? 09216080A3
Standard Cyl #? 35
Standard Expiration? 05/05/2018
Oper No? 029710

Flow Cal. Date: 06/20/2013
Slope 677
Intercept -702620

IR Calibration Date: 05/23/2016

	3um	9um
0th Coef(*100):	-18991	-21118
1st Coef(*100):	279327	139901
2nd Coef(*100):	2381	1164
H2O adj(mg/l*10k):	414	363

***** Printer Test End *****



Operator Signature
PATRICK RENZ

Remarks: *New Intoxilyzer Install*

Intoxilyzer Test Record and Checklist
NDOAG Crime Lab. Div., Bismarck, ND 58501

CMI, Inc. Intoxilyzer Alcohol Analyzer
North Dakota Model 8000 SN 80-005944
Location = BSPD 8164.13.00 06/09
07/28/2016 09:47

DRY CAL CHECK

Test	AC	Time
01 Room Air	0.000	09:48
02 Std. Gas	0.079	09:48
03 Room Air	0.000	09:48
04 Std. Gas	0.079	09:49
05 Room Air	0.000	09:49
06 Std. Gas	0.079	09:50
07 Room Air	0.000	09:50

Lot No = 09216080A3

Cyl No = 35

Exp Date = 05/05/2018

County = 08

Oper No. = 029710

Pat Renz

Operator Signature
PATRICK RENZ

Remarks: *New Intoxilyzer Install*

Form 106-I8000

Intoxilyzer Test Record and Checklist
NDOAG Crime Lab. Div., Bismarck, ND 58501

CMI, Inc. Intoxilyzer Alcohol Analyzer
North Dakota Model 8000 SN 80-005944
Location = BSPD 8164.13.00 06/09
07/28/2016 09:50

DRY CAL CHECK

Test	AC	Time
01 Room Air	0.000	09:51
02 Reference	RFI*	09:51
03 Room Air	0.000	09:52

*Invalid Test
Inhibited - RFI

Lot No = 09216080A3
Cyl No = 35
Exp Date = 05/05/2018
County = 08 Oper No. = 029710

Pat Renz

Operator Signature
PATRICK RENZ

Remarks:

New Intoxilyzer Install

Form 106-I8000