

INTOXILYZER® 8000 INSTALLATION AND REPAIR CHECKOUT

Serial No.: 80-^{004206 DK}6042006 Instrument Location: UND-PO

Reason for Install/Repair: Install After Lab Repair/Inspection
 Other (Specify) _____

Check When Done:

- A. Surge Protector Installed/Properly Grounded.
- B. Telephone Line Connected to Intoxilyzer®.
- C. Breath Tube Heated.
- D. Review/Enter Preliminary Data Entry (Level 2, Function E).
- E. Review/Enter Gas Setup (Level 1, Function S).
- F. Print Test (Level 1, Function P). (Attach Test Record.)
- G. ACA Test (Level 1, Function C). (Attach Test Record.)
- H. RFI Test (Use CMS Mode-First Room Air). (Attach Test Record.)
- I. Repair and/or Maintenance Performed: None

11-14-2009
Date

L. Tracy L. Mindinger #258
Field Inspector's Signature

17 NOV 2009
Date

Deb Kashur
Reviewed By

Intoxilyzer Test Record and Checklist
NDOAG Crime Lab. Div., Bismarck, ND 58501

CMI, Inc. Intoxilyzer Alcohol Analyzer
North Dakota Model 8000 SN 80-004206
Location = UNDP 8164.13.00 06/09
11/14/2009 19:11

DRY CAL CHECK

Test	AC	Time
01 Room Air	0.000	19:11
02 Std. Gas	0.082	19:12
03 Room Air	0.000	19:12
04 Std. Gas	0.083	19:13
05 Room Air	0.000	19:13
06 Std. Gas	0.082	19:14
07 Room Air	0.000	19:14

Lot No = 659358
Cyl No = 31
Exp Date = 09/03/2011
County = 18 Oper No. = 119409

Tracy L. Meidinger #258
Operator Signature
TRACY L. MEIDINGER

Remarks:
ACA (Level, function e.)

Form 106-I8000

*80-004206
1.3 of 4 FW*

Intoxilyzer Test Record and Checklist
NDOAG Crime Lab. Div., Bismarck, ND 58501

CMI, Inc. Intoxilyzer Alcohol Analyzer
North Dakota Model 8000 SN 80-004206
Location = UNDP 8164.13.00 06/09
11/14/2009 19:16

Test	AC	Time
01 Diagnostic	OK	19:18
02 Room Air	RFI*	19:18
03 Room Air	0.000	19:19

*Invalid Test
Inhibited - RFI

Sub Name = TEST, SUBJECT L
Sub DOB = 11/11/1911
Sub Sex = Male Weight = 215
Test = OTH Cit = 1111111111
Dr. Lic. = ND/1111111111
Lot No = 659358
Cyl No = 31
Expiration Date = 09/03/2011
County = 18 Oper No. = 119409

I followed the Approved Method and the instructions displayed by the Intoxilyzer in conducting this test.

Tracy L. Meidinger #258

Operator Signature
TRACY L. MEIDINGER

Remarks:

RFI Test (Custom Mode - First Room Air)

Form 106-I8000

80-004206
p. 4 of 4
JPL