



INTOXILYZER® 8000 INSTALLATION AND REPAIR CHECKOUT
OFFICE OF ATTORNEY GENERAL
CRIME LABORATORY DIVISION
 Toxicology Section/Breath Alcohol Program
 SFN 58281 (1-2010)

Serial Number: ^{OK} 80-003071	Instrument Location: TIOGA P.D.
Reason for Install/Repair:	
<input type="checkbox"/> Install After Lab Repair/Inspection <input checked="" type="checkbox"/> Other (Specify) <u>MOVED TO ANOTHER ROOM</u>	

Check When Done:

- A. Surge Protector Installed/Properly Grounded.
- B. Telephone Line Connected to Intoxilyzer® 8000.
- C. Breath Tube Heated
- D. Review/Enter Preliminary Data Entry (Level 2, Function E).
- E. Review/Enter Gas Setup (Level 1, Function S).
- F. Print Test (Level 1, Function P). (Attach Test Record.)
- G. ACA Test (Level 1, Function C). (Attach Test Record.)
- H. RFI Test (Use CMS Mode-First Room Air). (Attach Test Record.)
- I. Repair and/or Maintenance Performed: _____

[Signature]
 Field Inspector Signature

11/24/10
 Date

Deb Kasher
 Reviewed By

^{OK}
25 16 Feb 2011
 Date

80-003071
 P. 108 of 111
 KM

Intoxilyzer Test Record and Checklist
NDOAG Crime Lab. Div., Bismarck, ND 58501

CMI, Inc. Intoxilyzer Alcohol Analyzer
North Dakota Model 8000 SN 80-003071
Location = TIOG 8164.13.00 06/09
11/24/2010 23:06

***** Printer Test *****

abcdefghijklmnopqrstuvwxyz1234567890- = |
ABCDEFGHIJKLMNopQRSTUVWXYZ!@#\$\$%^&*()_+?

abcdefghijklmnopqrstuvwxyz1234567890- = |
ABCDEFGHIJKLMNopQRSTUVWXYZ!@#\$\$%^&*()_+?

Current Instrument Setup

Data Entry Mode: Enabled
Start Test Sequence: DABACABA
Display Prelim Rslt? Yes
Display Third Digit? Yes
Inhib Printer(Y/N)? No
Display Volume? No
Disable On Memfull? Yes
of Print Copies? 1
Select Std (D/W/I)? Dry
Standard Value? 0.080
Standard Lot #? 15410080A1
Standard Cyl #? 25
Standard Expiration? 07/01/2012
Oper No? 020632

Flow Cal. Date: 07/09/2010
Slope 806
Intercept -994737

IR Calibration Date: 07/09/2010
3um 9um

	3um	9um
0th Coef(*100):	-16015	-11994
1st Coef(*100):	278129	138369
2nd Coef(*100):	1927	1066
H2O adj(mg/l*10k):	293	137

***** Printer Test End *****



Operator Signature
SHANNON P. DUISEN

Remarks:


Intoxilyzer Test Record and Checklist
NDOAG Crime Lab. Div., Bismarck, ND 58501

CMI, Inc. Intoxilyzer Alcohol Analyzer
North Dakota Model 8000 SN 80-003071
Location = TIOG 8164.13.00 06/09
11/24/2010 23:18

DRY CAL CHECK

Test	AC	Time
01 Room Air	0.000	23:18
02 Std. Gas	0.079	23:19
03 Room Air	0.000	23:19
04 Std. Gas	0.078	23:20
05 Room Air	0.000	23:20
06 Std. Gas	0.078	23:21
07 Room Air	0.000	23:21

Lot No = 15410080A1
Cyl No = 25
Exp Date = 07/01/2012
County = 53 Oper No. = 020632


Operator Signature
SHANNON P. DUISEN

Remarks:

2nd ACA INSTALL

Form 106-I8000

80-003071
P. 110 of 111
SM

Intoxilyzer Test Record and Checklist
NDOAG Crime Lab. Div., Bismarck, ND 58501

CMI, Inc. Intoxilyzer Alcohol Analyzer
North Dakota Model 8000 SN 80-003071
Location = TIOG 8164.13.00 06/09
11/24/2010 23:39

Test	AC	Time
01 Diagnostic	OK	23:42
02 Room Air	0.000	23:43
03 *Subject Test	RFI*	23:43
04 Room Air	0.000	23:43

*Invalid Test
Inhibited - RFI

Sub Name = TEST, JOE NMN
Sub DOB = 02/16/1973
Sub Sex = Male Weight = 200
Test = DUI Cit = 00000001
Dr. Lic. = ND/TES731111
Lot No = 15410080A1
Cyl No = 25
Expiration Date = 07/01/2012
County = 53 Oper No. = 020632

I followed the Approved Method and the instructions displayed by the Intoxilyzer in conducting this test.



Operator Signature
SHANNON P. DUISEN

Remarks:

Form 106-I8000

80-003071
P. 111 of 111
PM